


Cabling twall® D1 - solid version



The following describes the installation of the connection lines for the twall® D1 (solid variant).

1x control box (1)

1x power adapter (2) with XLR socket, 3-pin (2.1)

Connect the 3-pin socket (2.1) to the control box (1), **POWER IN** input.

1x terminating resistor (3)

Plug the terminating resistor (3) into the socket of the module.

1x power CAN cable (4) with XLR plug, 4-pin (4.1) and XLR socket, 4-pin (4.2)

Connect the plug (4.1) with the control box (1), socket **TWALL OUT**.

Connect the socket (4.2) with the plug of the module.